

PLEASE READ THIS AND MAKE SURE THAT ANY EMPLOYEE THAT MAY HANDLE BUMPER COVERS IS AWARE OF OUR POLICY.



Many of the manufacturers that we deal with package their bumper covers in plastic bags with foam protection. Bumper covers packaged in this manner must be opened at the factory seal. This is usually at one end and would be opened like a loaf of bread. Many covers we receive for credit whether damaged or not needed, are sliced lengthwise with a razor knife. With most of our suppliers, this results in denial of credit, no matter what the reason the part was returned for. We will be strictly enforcing this policy. Any cover returned to TPC that has been sliced lengthwise or is missing any of the original packaging or part number, will to returned to the repair shop and no credit will be issued. Please help us avoid denying your shop credit by notifying your technicians of this policy. Thank you, we appreciate your business and cooperation.

Tonkin
PARTS CENTER

(503) 546-6900
(877) 787-2787